

COMMITTED TO EXCELLENCE

DATE: May 1, 2008

TO: Ann Beckel, Principal

SUBJECT: Tom Hicks ES - IAQ - Rooms F-103 & D-203

On Tuesday 4/29, I received W.O. #94472: "F-103 leak behind the bathroom wall-- mold growing". That afternoon, I inspected the room. It was wet along the wall between the restroom door and the crawl space door. I called the East Zone to send someone out to fix the leak, and set up fans and de-humidifier. This afternoon 5/1, I again inspected the room and it was dry and the leak had been fixed. I will request EFI to do an Air Test tomorrow.

This morning 5/1, I received an E-mail from Lana Barker: "Per counselor, Sonya Meadows, classroom D-203 has a strong odor of mold". I inspected the room this afternoon 5/1, and will request EFI to do an Air Test.

We should have the results back by Tuesday 5/6. If you have any questions, please call me.

Thanks,
Paul

Paul Siddall
Special Projects (IAQ)
Facility Services
469-446-8882